## **BRONZE GATE VALVE**

Screwed Bonnet, Non-rising Stem Threaded ends to BS21 (JIS B0203) or NPT, or solder joint ends.


W.O.G. non-shock 1.38 MPa (200 psi), Saturated steam pressure 0.86 MPa (125 psi)

3/8 to 2 Screwed-over-bonnet



## Fig. H

Threaded end to BS21 (JIS B0203)



## Materials

Parts	Material				
Body	Bronze				
Bonnet	Bronze				
Stem	Dezincification Resistant Brass				
Disc	Dezincification Resistant Brass/Bronze*				
Gland Packing	Aramid Fibers Graphite				

\*Size 3/4 & larger

Solder joint end valves should not be used in service where the temperature of line fluid is higher than the softening point of solder.

⚠ Don't use for Flammable gas or Toxic gas.

D	i	m	ıe	n	S	io	n	ς
$\boldsymbol{\nu}$		••	ľ		9	v		3

Dimensions											mm
Nominal Size	inch	3/8	1/2	3/4	1	11/4	11/2	2	21/2	3	4
	mm	10	15	20	25	32	40	50	65	80	100
		42	45	50	57	61	67	74	90	100	121
<b>L1</b> Solder		39	46	61	72	78	87	102	115	130	173
Н		74	80	90	105	118	135	159	202	223	280
D		50	50	55	60	70	80	90	115	135	155