

WEKSLER[®] Gauge Accessories



SIPHONS

When a gauge is to be used for steam pressures, a siphon filled with water is recommended between the line and gauge to prevent high temperature steam from entering the gauge bourdon tube.

TYPE NO.	SIZE	SIPHON MATERIAL	CAPACITY
A03I	1/4 NPT	Iron (Schedule 40)	500 psi and 400°F